



**MATERIAL
HANDLING**

Papé Material Handling, Inc., PO Box 987, Eugene, OR 97440

INVOICE DATE	INVOICE NO.
* 8-21-25	2478327

SERVICE INVOICE

PD ✓ 208Z
HID

This sale is subject to Papé's Terms and Conditions of Sale and reference. The Terms and Conditions of Sale are available at the purchaser upon request.

RIC I

98277

C

277

CUS		DATE OPENED 3-13-23	PURCHASE ORDER NO. NEED PO	AUTHORIZED BY / RELEASE NO.	
MAKE GE	MODEL GS3369BE	SERIAL NO. GS6915-6355	EQUIP NO.	METER	2
QUANTITY	DESCRIPTION	EACH	AMOUNT		
SEGMENT 002	DIAGNOSE ELECTRONIC DIAGNOSTIC TEST. 3/13 LOCATE UNIT, FOUND CHARGER STATUS LIGHT ON GREEN, BATTERIES AT 51.2V STATIC, INDICATES THAT CHARGER RAN FULL CYCLE AND TURNED OFF A WHILE AGO, VOLTAGE HAS SETTLED AFTER SITTING FOR SOME TIME. CONNECT METER AND TEST DRIVE UNIT WITHOUT GENERATOR RUNNING, AFTER 2MIN FOUND VOLTAGE DIPPING BELOW 40V WHEN DRIVING UP MINOR SLOPE, STATIC VOLTAGE SETTLES AROUND 49.9V. WARM UP GENERATOR AND REPEAT TESTS, SIMILAR RESULTS EXCEPT VOLTAGE CONTINUES TO RAISE WHILE SITTING. CHECK CHARGER OUTPUT, AT 51V MEASURED 30A ON GENERATOR, AND 20A ON WALL CHARGER. REPEAT TEST DRIVE WITH AMP CLAMP ON B+ CABLE AND GENERATOR OFF, PEAK DRAW MEASURED AT 306A WHILE DRIVING UP THE SLOPE. AFTER HARD 15MIN TEST DRIVE, STARTING WITH BATTERIES AT FULL STATE OF CHARGE, NO ERROR CODES WERE SET. GIVEN THE RATE OF DISCHARGE DURING OPERATION AND THE RATE OF CHARGE VIA GENERATOR OUTPUT, THE GENERATOR WILL NOT POWER THE UNIT WHOLLY ON ITS OWN, IT WILL SUPPLEMENT THE BATTERY OUTPUT DURING USE AND RECHARGE THEM WHEN RUNNING BUT NOT OPERATING. IF THE CUSTOMER DOES NOT CHARGE THE LIFT EVERY NIGHT BEFORE/AFTER USE, THE BATTERIES WILL BE DRAWN DOWN BELOW THEIR OPERATING RANGE AND SET ERROR CODES DURING OPERATION. AT THE VERY LEAST, IF UNIT IS BELOW 50% STATE OF CHARGE, RECOMMEND STARTING AND RUNNING GENERATOR FOR 30-60MIN PRIOR TO USE, AND SHOULD REMAIN RUNNING IF UNIT IS IN USE FOR MORE THAN A FEW MINUTES AT A TIME. DETERMINED THAT CHARGERS AND BATTERIES ARE WORKING AS DESIGNED, "LOW VOLTAGE" CODES ARE LIKELY DUE TO BATTERIES BEING DRAWN DOWN BELOW OPERATIONAL RANGE. BEST PRACTICE IS CHARGING UNIT THE NIGHT PRIOR TO WORK AND USE GENERATOR TO KEEP BATTERIES NEAR FULL STATE OF CHARGE				
Payment should be by cash, check or ACH/wire transfer		DESCRIPTION	AMOUNT		
SUBMIT PAYMENTS ONLY TO: Papé Material Handling PO Box 35144 #5077 Seattle, WA 98124-5144		TOTAL PARTS			
		TOTAL LABOR			
www.papemh.com		PLEASE PAY > THIS TOTAL >	CONTINUED		



**MATERIAL
HANDLING**

Papé Material Handling, Inc., PO Box 987, Eugene, OR 97440

INVOICE DATE	INVOICE NO.
* 8-21-25	2478327

SERVICE INVOICE

This sale is subject to Papé's Terms and Conditions of Sale effective reference. The Terms and Conditions of Sale are available at [www.papemh.com](#) the purchaser upon request.

Bill by this
e-mail to

IC I

3277

IC

3277

CUSTOM		DATE OPENED 3-13-23	PURCHASE ORDER NO. NEED PO		
MAKE GE	MODEL GS3369BE	SERIAL NO. GS6915-6355	EQUIP NO.	METER 2	
QUANTITY	DESCRIPTION		EACH	AMOUNT	
SEGMENT 001					
CHECK CODES/STOPS WORKING WHEN CODES SET CAN RESTART MACHINE AND CONTINUE WORKING SEE ATTACHED WORKORDER ***DO ANSI*** DIAGNOSE ELECTRONIC DIAGNOSTIC TEST. REPLACE BATTERY. GOT UNIT ,BATTERY DEAD PUT ON CHARGE FOUND 3 V AT MAIN PLUG OF BATTERY THEN CHECKED POWER TO CHARGERS ONLY ONE HAS POWER, THE TRACED POWER TO JUNCTION BOX AND FOUND BURNT WIRE AND BAD RELAY, NEED TO REPLACE RELAY THEN TEST CHARGERS AND SEE IF UNIT WILL POWER UP					
8	4200477	DEEP CYCLE B	371.50	2,972.00	
2	800049874	CONTACT KIT@	16.27	32.54	
2	NP192-4	RELAY	30.74	61.48	
4	215488GT	FUSE, 325 AMP	68.24	272.96	
1	230485GT	MOTOR W/TAC@	1,808.24	1,808.24	
1	230488GT	MOTOR CONTRO	1,091.42	1,091.42	
1	230488GT	MOTOR CONTRO	1,107.80	1,107.80	
1	232523GT	MOTOR, DRIVE@	2,380.57	2,380.57	
1	232523GT	MOTOR, DRIVE@	2,144.68	2,144.68	
1	824954GT	MODULE, CURR	1,121.82	1,121.82	
1	826709GT	RELAY, DPDT, 1	36.11	36.11	
FREIGHT				182.40	
FREIGHT				211.76	
FREIGHT				145.23	
PARTS		LABOR			
13,569.01		5,256.10	TIME/MATERIALS 18,825.11		
1,261.93		488.80	STATE/LOCAL TAX 1,750.73		
			SEGMENT TOTAL--> 20,575.84		
Payment should be by cash, check or ACH/wire transfer			DESCRIPTION	AMOUNT	
SUBMIT PAYMENTS ONLY TO: Papé Material Handling PO Box 35144 #5077 Seattle, WA 98124-5144			TOTAL PARTS		
			TOTAL LABOR		
www.papemh.com			PLEASE PAY > THIS TOTAL >	CONTINUED	



**MATERIAL
HANDLING**

Papé Material Handling, Inc., PO Box 987, Eugene, OR 97440

INVOICE DATE	INVOICE NO.
* 8-21-25	2478327

SERVICE INVOICE

This sale is subject to Papé's Terms and Conditions of Sale effective on the date hereof, which are incorporated in full by this reference. The Terms and Conditions of Sale are available at www.pape.com/terms and will also be sent by mail or e-mail to the purchaser upon request.

IC I

3277

SHIP
TO

RIC

38277

CUSTOM		DATE OPENED 3-13-25		NEED PO	
MAKE GE	MODEL GS3369BE	SERIAL NO. GS6915-6355	EQUIP NO.	METER 2	
QUANTITY	DESCRIPTION			EACH	AMOUNT
SEGMENT 002 CONTINUED DURING USE.					
PARTS .00 .00	LABOR 245.00 22.78			TIME/MATERIALS STATE/LOCAL TAX SEGMENT TOTAL-->	245.00 22.78 267.78
Payment should be by cash, check or ACH/wire transfer					
SUBMIT PAYMENTS ONLY TO: Papé Material Handling PO Box 35144 #5077 Seattle, WA 98124-5144				DESCRIPTION	AMOUNT
				TOTAL PARTS	13,569.01
				TOTAL LABOR	5,501.10
				STATE/LOCAL TAX	1,773.51
TERMS: PAYMENT DUE 08/31/25				PLEASE PAY >	20,843.62
www.papemh.com				THIS TOTAL >	