

09/20/18 PAPE' MACHINERY * W.O.#- 2339215 16:27:26 * BRANCH- 23 FINAL PREVIEW DIVISN- 04 PAGE- 01 WORK ORDER- 2339215 TRUCK NUM- 0 SHIP TO: 120 DAYS NO PAYMENT SOLD TO: 207860 J R HAYES & SONS INC POWERPLAN 22430 SE 231ST ST PHONE- 425-392-5722 MAPLE VALLEY WA 98038 P.O. #- NEED MAKE/MODEL- CT D5C DATE OPENED- 8/20/18 EQUIP. NUMBER- C33 SERIAL NUMBER- 5XK24922 SALE TYPE- 2 CHARGE SHOP/FLD/RES- S METER- 8437 _____ ord b-o ship rate extension --date----hrs-mech------S/F/R/Q-S JC- 0/ 0 LC-10 PC-10 NETTING PARTS SEGMENT 001 REMOVE AND REPLACE TRACK GROUPS, BOTTOM ROLLERS, TOP ROLLERS SPROCKETS AND IDLERS R-R AND REPLACE COMPLETE UNDERCARRAGE.CUT ROCK GAURD HARDWARE STRAP AND ROCK GAURDS THAT WELDED ON. EACH BOLT HAS A LOCK STRAP WELDED OVER IT AFTER TRACK FRAMES WERE REMOVED, I STARTED CUTTING ROCK GUARDS OFF. ROCK GUARDS WERE WELDED ON THE OUTSIDE AND ALSO ON THE INSIDE. THE INSIDE WELDS COULD NOT HAVE BEEN REMOVED WHILE TRACK FRAME WAS INSTALLED ON THE MACHINE.ALL THE THROUGH BOLT NUTS WERE WELDED ONTO THE THREADS OF THE BOLT. ALL THROUGH BOLTS HAD TO BE REPLACED . ALL ROCK GUARD BOLTS WERE WELDED WITH A STRAP FROM BOLT HEAD TO ROCK GUARD. AFTER ROLLERS WERE ALL INSTALLED AND ROCK GUARDS WERE BOLTED BACK ON ROCK GAURD WERE WELDED BACK INTO PLACE. 288 288

09/20/18 16:27:26 PAGE- 02	PAPE' MACH FINAL PR	INERY * W.O.#- 2339215 BRANCH- 23 EVIEW DIVISN- 04
WORK ORDER- 23392	15	TRUCK NUM- 0
SOLD TO: 207860 J R HAYES 22430 SE 2	& SONS INC	SHIP TO: 120 DAYS NO PAYMENT POWERPLAN
MAPLE VALI		PHONE- 425-392-5722 P.O. #- NEED DATE OPENED- 8/20/18
EQUIP. NUMBER- C33 SERIAL NUMBER- 5XK2 METER- 8437	4922	SALE TYPE- 2 CHARGE SHOP/FLD/RES- S
ord b-o ship		
		C- 0/ 0 LC-10 PC-10 NETTING PARTS
PARTS 8,863.20 886.31	LABOR SPEC SE 5,130.00 26 513.00 2	RVICES .94 BILLED TIME/MAT 14,020.14 .69 TAX 1,402.00 SEGMENT TOTAL> 15,422.14
SEGMENT 002	REPAIR BROKEN BOLTS AFTER TRACK FRAMES WERE 26 BROKEN BOLTS, MOST	C- 0/ 0 LC-10 PC-10 NETTING PARTS DISASEMBLED THERE WAS A TOTAL OF HAD TO BE TORCHED OUT . 7SEGMENT WN SO MUCH HAD TO BE TORCHED AND
PARTS .00	LABOR SPEC SE 2,480.63 233.55	
SEGMENT 003	REPAIR TRACK FRAMES TRACK FRAMES WERE WORN BACK TO SPEC. TRACK FRAMES SCARFED OUT CRACKS AND	C- 0/ 0 LC-10 PC-10 NETTING PARTS AT IDLERS. WELDED UP WORN AREAS MES WERE CRACKED IN SEVERAL SPOTS. REWELDEDONE OF THE CRACKS WENT LE . I PUT A HEAVY WALL INCERT INTO LDED UP THE CRACK.
PARTS .00	LABOR SPEC SE 902.81 83.03	RVICES .00 TIME/MATERIALS 902.81

09/20/18 16:27:26 PAGE- 03	PAPE' MACH FINAL PRI	INERY * W.O.#- 2339215 BRANCH- 23 EVIEW DIVISN- 04
WORK ORDER- 2339	9215	TRUCK NUM- 0
SOLD TO: 207860 J R HAYES 22430 SE) S & SONS INC 231ST ST	SHIP TO: 120 DAYS NO PAYMENT POWERPLAN
MAPLE VAI	LLEY WA 98038	PHONE- 425-392-5722
MAKE/MODEL- CT D50 EQUIP. NUMBER- C33	3	DATE OPENED- 8/20/18
SERIAL NUMBER- 5XE	K24922	SALE TYPE- 2 CHARGE SHOP/FLD/RES- S
ord b-o ship)	rate extension
SEGMENT 004 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	S/F/R/Q-S JO REPAIR BLADE PIN AND BUS REMOVED BLADE C-FRAME PO TO ACCESS BROKEN BEARING CARRER THAT WAS DAMAGED BLADE, TORQUED CARRIER IN LINE AND GREASED PIVIOTS 146-1679 BOLT EYE 308-1845 SEAL 3B-8489 FITTING 3G-3259 SEAL A 3G-7875 GREASE TUBE 4T-5613 RING 4T-5613 RING 5T-5613 RING 5T-561	C- 0/ 0 LC-10 PC-10 NETTING PARTS SHING FOR C-FRAME LVIOT PINS AND PULLED C-FRAME FORWARD GS. REPLACE BEARINGS AND BEARING WHEN THE BEARING FAILED. REINSTALLED MOUNTING HARDWARE. REPLACED GREASE 5. 268.82 537.64 23.29 46.58 1.51 3.02 34.97 69.94 23.00 46.00 14.69 29.38 92.35 184.70 5.97 11.94 12.73 25.46
954.66	1,115.44 98.15	.00 TIME/MATERIALS 2,070.10 TAX 98.15 SEGMENT TOTAL> 2,168.25
SEGMENT 098	S/F/R/Q-S JOOUTBOUND INSPECTION	C- 0/ 0 LC-10 PC-10 NETTING PARTS
PARTS .00	LABOR SPEC SEL .00	RVICES .00 TIME/MATERIALS .00 SEGMENT TOTAL> .00
9,817.86 886.31		.94 BILLED TIME/MAT 19,473.68 .69 TAX 1,816.73
		INVOICE TOTAL> 21,290.41



C29 C30 C31 C32 C33



Site Development General Contractor CAT Small Dozer Service / Machine Inspection

Date:	4-21-17	Mechanic:	Brian		Mechanic	Hrs:
250 Hour Service:	<u>Z</u> 1	Annua	l Service:			SMR: \$343
Engine						
	Inspect / Check	Replace	Qty	Wt.	Sample	Notes
Engine Oil			35	1549	V	
Filters		V/				
Air Filters		V				
Fuel						
Fuel Screen	NH					
Water Sep	10	* [g]				
Coolant	1					
Belts						× į
Hoses						
			Hydrau	lic Ma	- 3 S /4/4 .	
	Inspect / Check	Replace	Qty	Wt.	Sample	Notes
Hydraulic Oil	1				1/	
Filters						
Hoses	V					
Cylinders & Bushings						
			Drive Tra	nin		
	Inspect /	Replace	Qty	Wt.	Sample	Notes
	Check					
Transmission	1					
Filters		- /				
Finals		4			1	
KALE STOLL WITE		Ge	neral Insp	ection		
	Inspect / Check	Grease				Notes
Blade,Edge,Bushings						
Blade Control	1/					
Brake Pedal						
Batteries & Cables						
Back Up Alarm	V					
Lights						
Seat Belt & Seat	1					
Horn	1/					
Glass & Wipers	1					
U/C & Rollers CKAIR FWHAKE	V					



MACHINERY



Preventative Maintenance Checklist

		ventative iviali	terraniee e			
CUSTOMER NAME				CUSTOMER NO		W.O. NO.
J R HAYES & SON	S IN			207860-3	2	343611
EQUIPMENT NO.	MODEL	SERIAL NO.				HOUR METER READING
C33	D5C	07PS01208				8621
OTHER		LO	CATION			
77/25 05	TI FOO HOUR	F14000 HOL		12000 1101	ID 🖂 4	000 HOUR
TYPE OF		□1000 HOU	K L] 2000 HOL	JK . ⊔4	000 HOUR
SERVICE						
=						
		FLUID/FILTER	S CHANG	ED		
	1 ENGINE OIL AND FILTER O	CHANGED?	3 HYDRA	ULIC FILTER CHA	NGED?	
	2 TRANSMISSION FILTER CH	IANGED?	4 FUEL F	ILTER CHANGED	AND SCREEN CLEAN	ED?
						.J
	00.0454	N EC TAVEN AND		VELC CUEC	WED	
	OIL SAMI	LES TAKEN ANI) FLUID LE	VELS CHEC	KED	
7 ENGINE	11 REAR	DIFF.	15 CIRC	CLE DR.	19 🗸	H/C/BRAKE
8 TRANS	=	S RF/LF		ED REDUCER	20	SWING DR.
9 HYDRAULIC		S RR/LR	-	DLE L R		COOLANTF
		EMS R L		RING		COOLAINI
10 FRONT DIFF	14 V IAND	EIVIS N. L	10 7 3166	INING		
OTHERS						
OTHERS:						
		CHEC	KED			
22 AIR FILTERS				ASED FITTINGS	46 🗸	SEAT BELT CONDITION
23 BATTERIES	31 AIR T/			ATHERS	47	SERVICE INTERVAL NOTIFICATION DECAL
24 ALTERNATO		JOINTS LTER INDICATOR		E EX CHG. CK ALARM		COMPLETED
26 GAUGES		CLEANER		AKE LIGHTS	48	FRONT AXLE BEARING (MTG)
27 HORN		COVERS		OSED WIRING	49	WORK LIGHTS
28 ROTATING I		SIGNALS		AB IRONS	50 /	COOLANT CONDITION
29 PARKING BE				PS/FOPS	51	GREASE PIVOT POINTS
						•
OTHER:						
		ALK AROUND V	SUAL INS	PECTION		
COMMENTS/RECOMM	IENDATIONS:					
NOTE: If assis	tance from Papé Machin	erv is required in				
	ig the above repairs, Plea					
	<u> </u>		<u> </u>		145 14 5	1
ABBREVIATIONS: Ye	es No RR = Requires Repair	OK = No Repair Requ	ired NA = N	ot Applicable	MF = Make up F	luid Added
BONNER, JAKOE	3	11-19- 201 9				
SERV	ICEMAN SIGNATURE		DATE		CUSTOMER S	IGNATURE

HITACHI DYNAPAC



C29 C30 C31 C32 C33

AS

Site Development General Contractor

CAT Small Dozer Service / Machine Inspection

Date:	946-22	Mechani	c: Brian		Mechanic I	trs: 2.5	
	A	Ann	ual Service:		SMR: 8906		
11.12			Engine				
S 100, 1000 110 1000	Inspect / Check	Replace	Qty	Wt.	Sample	Notes	
Engine Oil		V	3'9	1548		*.	
Filters							
Air Filters							
Fuel							
Fuel Screen	N-A-						
Water Sep	N						
Coolant	V						
Belts	1						
Hoses							
3			Hydraul	lic			
	Inspect / Check	Replace	Qty	Wt.	Sample	Notes	
Hydraulic Oil		:21					
Filters							
Hoses	V						
Cylinders & Bushings	V						
			Drive Tra	ain			
	Inspect / Check	Replace	Qty	Wt.	Sample	Notes	
Transmission							
Filters	V						
Finals	VV				0.201.000.000.000		
e/							
	40.7	(General Insp	ection			
	Inspect / Check	Grease			XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	Notes	
Blade,Edge,Bushings			1. Ridit blade Cul Leaking				
Blade Control							
Brake Pedal		2 Enc oil Leak Left Sido					
Batteries & Cables	V						
Back Up Alarm	1		3 Needs New Alt beits they are				
Lights			LOUSE & No More adjustment				
Seat Belt & Seat	V						
Horn							
Glass & Wipers							
U/C & Rollers	V						